



**Power Systems**

1400 East South Blvd • Montgomery, AL 36116  
(334) 286-8551 • (334) 286-8018 Fax  
<http://www.kellyaerospace.com>

# Service Information Letter

Bulletin No. A-109

Issue Date: September 17, 2002

## 200F SERIES FUEL PUMP REPLACEMENT NOTIFICATION

Kelly Aerospace Inc has determined the potential exists for fuel seepage around the rear cover of the following 200F Series fuel pump serial numbers:

<b><u>Serial Number:</u></b>	<b><u>Part Number:</u></b>
FEN001FP	200F-5002
FEN002FP	200F-5002
FEN003FP	200F-5002
FEN004FP	200F-5002
FEN005FP	200F-5002
FEN006FP	200F-5002
FEN009FP	200F-5002
FEN010FP	200F-5002
FEN012FP	200F-5002
FEN014FP	200F-5002
FEN016FP	200F-5002
FEN017FP	200F-5002
FEN018FP	200F-5002
FEN019FP	200F-5002
FEN020FP	200F-5002
FFN002FP	200F-5002
FFN020FP	200F-5002
FEN022FP	200F-5003
FEN032FP	200F-5004
FFN032FP	200F-5004

To address this potential Kelly Aerospace issues this Service Information Letter to inform the customer of the need for immediate, mandatory, replacement of these fuel pumps with a unit manufactured after August 1, 2002.

For questions concerning any issues related to this matter please contact Kelly Aerospace, Technical Services Department at 334-227-8306.