

## 94E47 OVERHAUL MANUAL - AIRCRAFT HEATER REV. B NOW AVAILABLE

### INTRODUCTION:

Kelly Aerospace Energy Systems issued Service Letter #024 which fully described the new change in revision service (see latest revision). An update and revision of the Aircraft Heater Overhaul Manual P/N 94E47 has been completed and is now available for insertion into your current manual. This revision incorporates several minor changes and adjustments. Any current owner of a P/N 94E47 Overhaul Manual with valid serial number may purchase this revision.

This Service Information Letter announces the availability of Rev. B of the 94E47 Overhaul Manual for Aircraft Heaters and serves to notify users of this manual of the current revision status..

### COMPLIANCE:

Insert revision B immediately upon receipt.

### EFFECTIVITY:

All P/N 94E47 Overhaul Manuals with valid serial numbers.

### PROCEDURE:

1. Determine the serial number of the manual in your possession. This may be found on the Registration page which is the first page of the manual. (serial numbers appear as 94E47- ...)
2. The manual revision may be ordered direct. Fax the completed form on page 3 of this SIL to Kelly Aerospace Energy Systems Customer Service (334) 386-5450.
3. Summary of information in this revision is shown on page 2.
4. Upon receipt of revision B, remove pages to be revised, discard and insert new pages. Black bars on the edge of the revised page indicate the area of revision. Black bars adjacent to the page number indicate new page or a majority change to that page. Because the Title page is being changed and for future reference, make sure that the manual serial number is recorded on the new page.

### PARTS AVAILABILITY:

This revision may be ordered and purchased directly from KAES, call for price quote.

### WARRANTY STATEMENT:

There is no warranty associated with this service publication or affected manual. Revision B must be purchased. This is regardless of when the original manual was purchased.

*For questions concerning this instruction please contact KAES, Service Dept. at (888) 461-6077.*

## Summary of Revision A:

New	1-27-07	--	Original Issue date
A	1-09-08	--	Issue date of Rev. A
B	3-16-09	Title Page	Modified address, change name
		ii	Update copyright
		vii	Changed name
		ix, x	Fix Rev A date error, add Rev B
		xix, xx	Corrected & Modified LOEP changed to 1-09-08
		xii	Updated info. to SPL
		A-1	Changed name
		1, 2, 4	Changed name
		6	Changed name definition
		9, 10	Changed name, update warranty
		11	Changed name, update warranty
		1-1	Changed name
		6-4	Added Fig. 62 footer
		7-1	Changed name
		9-1	Changed name
		9-2	Clarified 100 hour mandatory check, corrected item 2 format error, relocated item 10 info., changed name
		9-3	Added item 10 info., re-format page, changed name, clarified 500 hour task
		10-19	Changed name
		12-2	Changed name
		13-2, 13-8	Changed name, reformat notes
		13-9, 13-15	Changed name
		14-1	Changed name

**94E47 Heater Overhaul  
Manual Rev. B**



2900 Selma Highway  
Montgomery, AL 36108, USA  
(334) 386-5400 (334) 386-5450 FAX  
www.kellyaerospace.com

94E47 Heater Overhaul Manual  
Serial Number \_\_\_\_\_

Contact information:

Date:

Name: \_\_\_\_\_  
Company: \_\_\_\_\_  
Address: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Billing method:  Credit Card  PO No. \_\_\_\_\_  Other (specify) \_\_\_\_\_

Shipping Address: (if different)

Name: \_\_\_\_\_  
Company: \_\_\_\_\_  
Address: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Special Instructions:

Method of shipping:  UPS (1 day, 2 day, ground)  Fed Ex (1 day, 2 day, standard)  Other (specify) \_\_\_\_\_ (1 day, 2 day, standard, post)

Fax this completed form to Kelly Aerospace Energy Systems Customer Service department at (334) 386-5450.

Payments are accepted by money order, credit card (MasterCard, Visa only), and check (funds must clear the bank before shipment).

**Ship To:** (your address below)